


# Wiring Diagrams

## BELT DRIVE AXIAL 380V-440V THREE PHASE

FIXED SPEED  
STAR CONNECTION



FIXED SPEED  
DELTA CONNECTION

